


# BLACK BOX WIRING DIAGRAM FOR UP TO 3 MOTORS

TARP (MOTOR 1)

TRAP DOOR (MOTOR 2)



LIMIT SWITCHES  
FOR TRAP DOOR (MOTOR 2)  
(FLIP DIP SWITCHES 7 & 8)

LIMIT SWITCHES  
FOR TRAP DOOR (MOTOR 3)  
(FLIP DIP SWITCHES 9 & 10)

